

# HEALTHY COMFORTABLE DYNAMIC

To create a more comfortable working environment

## **Product Concept**

Bring performance to the office
It can carry more
Move faster
Be more environmentally friendly


Modern studies have shown that a sedentary life style is the culprit of various diseases, such as hypertension, heart disease and cervical and lumbar diseases.

Sedentary is defined by the WHO as the second main factor causing cripple.

The study also helplessly proves that a physical exercise after a long time sitting, cannot eliminate its harmful effects.

We must change the situation. Standing up, in order to move further.





## ■ Technical specs

√ Column Size: 80x80mm or 70x70mm

√ Height Range: 710-1210mm

√ Stroke: 500mm

 $\sqrt{\text{Length Custom}}$ : 1280mm or 1480mm or 1680mm


√ Length Custom Range: 1320mm-1720mm

 $\sqrt{\text{Foot base:}}$  Rectangular, Circular Arc

#### **■** Colour







## ■ Technical specs

√ Column Size: 80x80mm or 70x70mm

√ Height Range: 710-1210mm

√ Stroke: 500mm

 $\sqrt{\text{Length Custom: }}$  1280mm or 1480mm or 1680mm


 $\sqrt{\text{Length Custom Range: } 1320\text{mm}-1720\text{mm}}$ 

 $\sqrt{\text{Foot base:}}$  Rectangular, Circular Arc

#### ■ Colour







#### ■ Technical specs

 $\sqrt{\text{Column Size: }80\text{x}80\text{mm or }70\text{x}70\text{mm}}$ 

√ Height Range: 710-1210mm

√ Stroke: 500mm

√ Length Custom: 1280mm or 1480mm or 1680mm

√ Length Custom Range: 1320mm-1720mm

√ Foot base: Rectangular, Circular Arc


#### **■** Colour







## work and power





#### Security

No power supply is the most safest guarantee Multiple gears locking system can take 500KGS static load-bearing



#### **Durability**

The Low speed mechanical gear box runs with very low friction, Precision Guaranteed for 10 years.



## **Humanization design**

One switch to control open & locking



The power source is Suspending gas spring + Manganese steel torsional spring. To balance lift up and down will make you feel free and relaxed in use



Use turning wrench to add lifting force so as to meet the varying weights placed on the table.



Simple assembly frame, only divided into 5 components & only use 16 screws for assembly.